Rev Date: Section 058

1976

SHUTTLE SERIES BOBOLA DOCUMENTS

These files were collected by Robert Bobola between 1976 and 1981 when he was working in the Orbiter Project Engineering Office (mail code EK4). This is a preliminary inventory, no documents have been culled or re-arranged within the folders. The folders have been arranged alphabetically by subject and contain correspondence, reports, charts, and presentation material.

| Inventory | | | |
|-------------|---|--------------------|--|
| SubHeading: | Box Number: 1 | | |
| | Aerospace Safety Advisory Panel, Orbiter Configuration Differences OV- 99 vs OV102, build & Test Ov-104 vs OV-103, Centaur | August 23, 1984 | |
| | APU (Auxiliary Power Unit) | 1977-81 | |
| | APU Failure and Model Story | 1976-79 | |
| | APU History / F16 EPU Comparison | 1979-83 | |
| | APU Turbine Wheel Blade Failure | 1976 | |
| | Bellows Flow Lines | 1978 | |
| | Connectors | nd | |
| | DI-19 Multi-Environment Testing | May 31, 1979 | |
| | Dynatube Connector, Williams Committee, Propulsion 25 | May 9, 1980 | |
| | Dynatube Failure & Lockwire | 1976-77 | |
| | Dynatube Torquing | January 1979 | |
| SubHeading: | Box Number: 2 | | |
| | Ferry Flight #1, OV-102 | 1979 | |
| | Flexible Hoses | nd | |
| | Flight Control Hydraulics Laboratory Servo Failure | 1978 | |
| | Flow Control Valve Failure | 1982-84 | |
| | Freeze Proofing OV-102, CCB 9/20/78 | 1978-80 | |
| | Haydon Limit Switch Contamination Issue | 1984 | |
| | Huck Rivets | 1975 | |
| | H2O Boiler | 1982 | |
| | Hydraulic Research, Textron Elevon, Phase II Briefing | October 18, 1976 | |
| SubHeading: | Box Number: 3 | | |
| | Hydraulics | 1976 | |
| | Hydrazine Spill | 1977 | |
| | Launch Site Flight Operations | August 22, 1984 | |
| | Lightning Protection | 1979 | |
| | MDM Republic Capacitor Problem | September 15, 1976 | |
| | Mission Kit, MOD | 1981 | |
| | Mission Kits / Changes, Tabs, Lists, Printouts | 1980-81 | |
| SubHeading: | Box Number: 4 | | |
| | N2O4 Spill | 1978-81 | |
| | OMS Pod Contamination | June 1981 | |
| | OMS Pod Helium Tank Bracket | 1980 | |

Optical Isolators

| | Orbiter Landing Gear / Brakes | 1983 |
|-------------|--|-------------------|
| | Permaswage & Dynatubes | 1976 |
| | Permaswage Failure | 1980 |
| | RCS / Hydraulics Review | 1978 |
| | Reynolds Aluminum | August 1979 |
| | STS-1 APS Pod Flight Damage Assessment | April, 16, 1981 |
| | STS-2 Management Council | April 30, 1981 |
| | STS-2 Management Council & Requirements | 1981 |
| SubHeading: | Box Number: 5 | |
| | STS-2 Mods, Schedules, etc. | 1980-81 |
| | STS-2 schedule Scrub | 1981 |
| | STS-3 Kits, Working Group 8/25 | 1981 |
| | STS 3-5 | 1981 |
| | STS 3-6 Headquarters Briefing | 1981-82 |
| SubHeading: | Box Number: 6 | |
| | STS 3-5 Mods | 1981 |
| | STS 3-5 Planning Support Management Council July 17, Meeting with KSC / RI July 10 | 1981 |
| | STS 3-5 Work Status, Modifications | 1981 |
| | Toggle Switch Anomaly & Criticality Assessment, R16683, CCB 5/23, 8/7 | May - August 1978 |
| | TPS | 1982 |
| | Tubing | nd |
| | Window Covers, MCR 9471 | 1982 |
| | Wiring DITMCO (Dynamic Integrated Test Mission Control Operations) | 1976-79 |
| | | |